Company 1	Project Name			Logo 2					
Close Out Sheet									
PSD-HUC-063	MRU Barge Campaign Post Shutdown Phase CRA			Due Date:	2021-03-27				
Activity	Node	Facility		Priority					
	BRG-CPP								
Project Phase			Guideword						
MRU Integration Project Post-Shutdown Phase									
Causes									
Inadequate / incorrect inspection for new Ex-rated equipment, i.e. not performing detailed inspections for new equipment     Incompetent / Uncertified persons performing Ex-rated equipment installation, inspections and verifications, i.e. personnel without IECEx Certificate of Personnel Competence (CoPC)									
Safeguards									
Consequences  Source of ignition at hazardous classified area on platform during normal operations, leading to increased risks of fire and explosion in event of gas leaks									
Initial risk	Res	sidual Risk							
None	No	ne							
Recommendations/ Actions									
Contract requirement Supervisor with Ex-	ent for IECEx Certificate of Pernt for Ex equipment installation 003 and inspection of Ex-rated Plan and HUC work packs as r	and insp equipme	pection are imple ent (Ex-001/007	emented	i, e.g.				

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed