Company 1	Project Name			Logo 2				
Close Out Sheet								
PSD-HUC-087	MRU Barge Campaign Post S	Due Date:	2021-03-27					
Activity	Node	Facility		Priority				
			BRG-CPP					
Project Phase								
MRU Integration Project Post-Shutdown Phase								
Causes								
Incorrect work sequence, Work Interface issues for breaking of leak test spread / assembly								
Safeguards								
Consequences Projectiles due to trapped pressure hazards within equipment / piping system resulting in personnel injuries/ fatality and asset damage.								
Initial risk	Res	idual Risk						
	s and verifications to control tra		essure hazards a	are reflec	cted in			
Leak Test Procedur		•						

Response						
Remarks			Actionee			
Attachments						
Organisation	MMHE	Signature:	Date:			
Disipline and Subdisipline HUC		Signature:	Signature:		Date:	
COMPANY COMMENTS			Status			
					Agree	
					Agree with comments	
					Disagree	
					To be followed	
COMPANY Lead Discipline:		Signature:		Date:	•	
COMPANY Lead Safety:		Signature:		Date:		
COMPANY Rep (Engineering Coordinator):		Signature:		Date:		
The information contained in this document is the	proprietary to North Oil Company. It must not I uncontrolled and considered as "for information	be reproduced, stored, disclosed to any	third party or used for any purpose of the undated to the on-line EDMS for the undated	not authorized by Need version	lorth Oil Company. Printed	