Company 1	Project Name			Logo 2					
Close Out Sheet									
PSD-HUC-096	MRU Barge Campaign Post S	Due Date:	2021-04-10						
Activity	Node	Facility		Priority					
		l	BRG-CPP						
Project Phase			Guideword						
MRU Inte									
Causes									
Inadequate / incorrect work method statement, procedures and provisions to perform repairs at site									
Safeguards									
Consequences Unable to perform repairs and reinstatement of system, resulting in delays to complete work campaign and start-up of MRU modules									
Initial risk	Res	idual Risk							
None	Noi	ne							
Recommendations/ Actions									
To ensure Leak Test Procedure & Work Pack describe requirement for provision of spares for repair / reinstatement if leaks are detected on piping system (e.g. spare gaskets, etc.) and availability of personnel to perform these repairs (e.g. bolt tensioning)									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed