Company 1	Project Name				Logo 2				
Close Out Sheet									
PSD-HUC-113	MRU Barge Campaign Post Shutdown Phase CRA				2021-04-10				
Activity	Node			Priority					
Project Phase	BRG-CPP Guideword								
MRU Integration Project Post-Shutdown Phase									
Causes									
Spillage of adsorbents during filling activities - from cat cans									
Safeguards									
Consequences Adsorbent - Pyrophoric materials (Puraspec 1178 / 5199) - Self-healing material leading to potential fire									
- Source of ignition at live platform leading to increased risk of fire and explosion, in event of gas leaks, resulting in personnel injuries / fatalities, major asset and environmental impact.									
Initial risk	Res	idual Risk							
None Recommendations / Action	Noi	ne							
Recommendations/ Actions To update work pack to reflect source of nitrogen for use as part adsorbent spill contingency									
procedure.	k to reliect source of hitrogen to	л use as	s part ausorbent	spili con	шпуепсу				

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	^{ne} Commissioninç	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
The information contained in this d	ocument is the proprietary to North Oil Company. It must documents are uncontrolled and considered as "for inform	not be reproduced, stored, disclosed to any nation only". Reference should always be ma	third party or used for any purpose of the to the on-line EDMS for the update	not authorized by Ned version	lorth Oil Company. Printed