Company 1	Project Name			Logo 2				
Close Out Sheet								
PSD-HUC-087	MRU Barge Campaign Post S	Due Date:	2021-04-10					
Activity	Node	Facility		Priority				
Project Phase		BRG-CPP Guideword						
-			Guideword					
MRU Integration Project Post-Shutdown Phase								
Causes Incorrect work sequence, Work Interface issues for breaking of leak test spread / assembly								
Safeguards								
Consequences Projectiles due to trapped pressure hazards within equipment / piping system resulting in personnel injuries/ fatality and asset damage.								
Initial risk	Res	sidual Risk						
Recommendations/ Actions To ensure checklists and verifications to control trapped pressure hazards are reflected in Leak Test Procedure & Work Packs								

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed