Company 1	Project Name			Logo 2				
Close Out Sheet								
PSD-HUC-068	MRU Barge Campaign Post S	Due Date:	2021-03-27					
Activity	Node	Facility		Priority				
			BRG-CPP					
Project Phase			Guideword					
MRU Integration Project Post-Shutdown Phase								
Causes								
Inadequate / unclear work instructions - for work at marshalling cabinet								
Safeguards								
Consequences Inadvertent trips causing disruptions to work activities at CPP requiring investigation, verification of safe work site or rectification works, or platform inadvertent shutdown								
Initial risk	Res	idual Risk						
None Recommendations/ Action To appure a Committee			oonnooting lysife	owitch 4	eorminal .			
To ensure a Commissioning Work Pack is developed for reconnecting knife switch terminal block at FGS system panel FGS, upon reinstallation during Post-shutdown campaign.								

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed