Company 1	Project Name				Logo 2				
Close Out Sheet									
PSD-HUC-078	MRU Barge Campaign Post S	Due Date:	2021-04-10						
Activity	Node	Facility		Priority					
			BRG-CPP						
Project Phase Guidew									
MRU Integration Project Post-Shutdown Phase									
Causes									
Incorrect / inadequate lifting work plans - Inadequate or incorrect rigging, congested laydown area, lifting above load limits, multiple lifts									
Safeguards									
Consequences  Unsafe work conditions, unsafe acts leading to dropped / swing objects resulting in personnel injuries / fatality, platform asset and equipment damage, work campaign equipment damage and delays to complete work campaign.									
Initial risk	Res	sidual Risk							
None	Noi	20							
Recommendations/ Actions  To review and ensure appropriate lifting / rigging arrangement for N2 skid and equipment are provided for safe material transfer. To describe in Leak Test procedure / work pack.									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed