Company 1	Project Name				Logo 2				
Close Out Sheet									
PSD-HUC-014	MRU Barge Campaign Post Shutdown Phase CRA				2021-04-10				
Activity	Node	Facility		Priority					
		BRG-CPP							
Project Phase			Guideword						
MRU Inte									
Causes									
1. Incorrect / improper pressurized habitat installation at BRG CPP Hazardous Classified Area									
2. Improper / Lack of inspections and verifications of habitat set-up for safe operations									
Safeguards Safeguards									
Consequences Source of ignition causing Increased risk of fire & explosion in event of hydrocarbon LOPC, resulting in personnel injuries / fatalities, major platform asset and environmental impacts.									
Initial risk	Res	idual Risk							
None	Noi	ne							
Recommendations/ Actions									
To review Pressurized Habitat sizes based on planned work activities. To ensure adequate modular habitat provisions are made available at site to optimize habitat operations and controls, e.g. single habitat for work site in close proximity. To then update relevant HUC work packs and TEC list.									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed