Company 1	Project Name				Logo 2			
Close Out Sheet								
PSD-HUC-114	MRU Barge Campaign Post Shutdown Phase CRA				2021-03-27			
Activity	Node	Facility		Priority				
		I	BRG-CPP	-				
Project Phase Guideword								
MRU Integration Project Post-Shutdown Phase								
Causes								
Inadequate N2 purging - impurities, lack of displacement flow								
Safeguards								
None								
Adsorbent - Pyrophoric materials (Puraspec 1178 / 5199) - Self-healing material leading to potential fire - Source of ignition at live platform leading to increased risk of fire and explosion, in event of gas leaks, resulting in personnel injuries / fatalities, major asset and environmental impact.								
Initial risk	Res	idual Risk						
None	Noi	ne						
Recommendations/ Actions								
To confirm that Post-Shutdown Leak Test work pack includes monitoring requirement, continuous manning of N2 skid during N2 purging activities and communication protocols with adsorbent filling team.								

Response						
None						
Remarks			Actionee			
Attachments						
Organisation	MMHE	Signature:	Date:			
Disipline and Subdisiplin	ne HUC	Signature:		Date:		
COMPANY COMMENT	rs			Status		
					Agree	
					Agree with comments	
					Disagree	
					To be followed	
COMPANY Lead Discipli	ne:	Signature:		Date:		
COMPANY Lead Safety:		Signature:		Date:		
COMPANY Rep (Engineering Coordinator):		Signature:		Date:		
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed	