Company 1	Project Name				Logo 2				
Close Out Sheet									
PSD-HUC-043	_								
Activity	Node	Facility		Priority					
			BRG-CPP						
Project Phase Guideword									
MRU Integration Project Post-Shutdown Phase									
Causes									
Unclear work plan, Incorrect work sequencing with Structural work activities									
Safeguards									
Consequences Disruptions to other discipline planned work activities, resulting in delays to complete work campaign									
Initial risk	Res	idual Risk							
None	No	ne							
Recommendations/ Actions									
To review work sequence and work area control to perform Blasting and PFP coating, e.g. Blasting activities should not be performed in close proximity to PFP coating, etc.									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed