Company 1	Project Name			Logo 2				
Close Out Sheet								
PSD-HUC-066	MRU Barge Campaign Post Shutdown Phase CRA			Due Date:	2021-03-27			
Activity	Node	Facility		Priority				
			BRG-CPP					
Project Phase			Guideword					
MRU Integration Project Post-Shutdown Phase								
Causes								
Incorrect work sequence, Work Interface issues for isolation and draining of instrument tubing from Hydrocarbon piping system								
Safeguards								
Consequences  1. Hydrocarbon spillage at work site, leading to potential fire, if ignited, resulting in personnel injuries/ fatality and asset damage.  2. Projectiles due to trapped pressure hazards resulting in personnel injuries and asset damage.								
Initial risk	Res	idual Risk						
None	No	ne						
Recommendations/ Actions								
To ensure work plan and work activity controls for removing of PDIT including safe isolation of instrument, tubing disconnection, draining and mercury hazard control, are included in a HUC work pack and JSA. To also include reinstallation of tubing and required leak tests in this HUC work pack.								

Response						
None						
Remarks			Actionee			
Attachments						
Organisation	MMHE	Signature:	Date:			
Disipline and Subdisiplin	ne HUC	Signature:		Date:		
COMPANY COMMENT	rs			Status		
					Agree	
					Agree with comments	
					Disagree	
					To be followed	
COMPANY Lead Discipli	ne:	Signature:		Date:		
COMPANY Lead Safety:		Signature:		Date:		
COMPANY Rep (Engineering Coordinator):		Signature:		Date:		
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed	