Company 1	Project Name				Logo 2			
Close Out Sheet								
PSD-HUC-071	MRU Barge Campaign Post Shutdown Phase CRA				2021-03-27			
Activity	Node	Facility	acility					
			BRG-CPP					
Project Phase	Guideword							
MRU Integration Project Post-Shutdown Phase								
Causes								
Loss of power to lighting and essential equipment during night work activities - Platform and Work Area								
Safeguards								
Consequences  Unsafe conditions, Unsafe acts - resulting in personnel injuries / fatality due to falls, incorrect handling of energized tools or equipment, falling from height, adverse weather, etc.and equipment / asset damage								
	P	ti inti						
Initial risk	Res	idual Risk						
Recommendations/ Actions  To review adequacy of lighting fixtures at N2 skid area and leak tests work activities area. If inadequate, to provide temporary lighting fixtures. To describe requirement in Leak Test Procedure.								

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed