Company 1	Project Name			Logo 2					
Close Out Sheet									
PSD-HUC-070	MRU Barge Campaign Post S	Due Date:	2021-04-10						
Activity	Node	Facility		Priority					
		BRG-CPP							
Project Phase									
MRU Inte									
Causes									
1. Improper / Inadequate work	control procedures, E.g. Leak test procedures, Wo	orkpack, work	instructions, JSA						
2. Human errors - Untrained / Incompetent personnel for work campaign activities, Unclear work roles and responsibilities, inadequate work supervision and coordination for work activities									
3. Mismatch of job tasks to personnel work activities - inadequate or unclear job requirements, unrealistic targets or job expectations									
Improper work interface planning and coordination - poor work interfaces, unclear reporting relationships, lack of clear planning, miscommunications									
Safeguards									
Consequences Incorrect / Improper execution of work activities leading to reworks or rectification works, project equipment / asset damage and delays to complete operations.									
Initial risk	Res	idual Risk							
None	Noi	ne							
Recommendations/ Actions									
-	ment for Leak Test Packs to be tart of works, in Leak Test proce	-	_	eak Test	Contractor				

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed