Company 1	Project Name			Logo 2				
Close Out Sheet								
PSD-HUC-047	MRU Barge Campaign Post Shutdown Phase CRA				2021-04-10			
Activity	Node	Facility		Priority				
		l	BRG-CPP					
Project Phase Guideword								
MRU Integration Project Post-Shutdown Phase								
Causes								
Improper work area isolation or controls for blasting activities								
Safeguards								
None								
Source of ignition at hazardous classified area on platform during normal operations, leading to increased risks of fire and explosion in event of gas leaks, resulting in personnel injuries / fatalities, major asset and environmental impacts								
Initial risk	Residual Risk							
None	No	ne						
Recommendations/ Actions								
To review Blasting work activity equipment set-up and assembly, and establish required work area control, e.g. compressor, loose tools, equipment, etc. To then update blasting procedure and work pack.								

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed