Company 1	Project Name			Logo 2					
Close Out Sheet									
PSD-HUC-075	MRU Barge Campaign Post Shutdown Phase CRA				2021-04-10				
Activity	Node	Facility		Priority					
Project Phase	Phase BRG-CPP  Guideword								
MRU Integration Project Post-Shutdown Phase									
Causes									
Improper storage of hazardous temporary equipment, e.g. pressurized Helium bottle storage     Deterioration of bottle manifold									
Safeguards									
Consequences Unsafe conditions, Projectiles - resulting in personnel injuries / fatality									
Initial risk	Res	idual Risk							
None  Recommendations/ Action	No	ne							
		the N2	ekid layout and	anguro M	ork area				
To ensure Helium bottle rack storage is reflected in the N2 skid layout and ensure work area restrictions requirement are reflected in the Leak Test Procedure, work pack and JSA.									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed