Company 1	Project Name				Logo 2			
Close Out Sheet								
PSD-HUC-045	MRU Barge Campaign Post Shutdown Phase CRA			Due Date:	2021-04-10			
Activity	Node	Facility		Priority				
		BRG-CPP						
Project Phase Guidew								
MRU Inte								
Causes								
Inadequate / Incorrect work control procedures for removal and collection of blasting garnet / debris								
Safeguards								
Consequences 1. Unsafe conditions from blasting garnet / debris at work areas and access ways leading to personnel injuries due to slips, trips or falls and asset impact requiring clean-up and repair / rectifications if damaged. 2. Personnel respiratory illness due to inhalation of blasting garnet / debris.								
Initial risk	Res	idual Risk						
Recommendations/ Actions To review existing Waste Management Procedure and ensure handling and disposal of garnet residue, blasting debris, etc. (air borne) are described including required equipment / tools.								

Response						
None						
Remarks			Actionee			
Attachments						
Organisation	MMHE	Signature:	nature: Date:			
Disipline and Subdisiplin	^{ne} Technical Safe	Signature:		Date:		
COMPANY COMMENT	TS			Status		
					Agree	
					Agree with comments	
					Disagree	
					To be followed	
COMPANY Lead Discipli	ine:	Signature:		Date:	•	
COMPANY Lead Safety:		Signature:		Date:		
COMPANY Rep (Engineering Coordinator):		Signature:		Date:		
The information contained in this d	document is the proprietary to North Oil Company. It mus documents are uncontrolled and considered as "for infor	it not be reproduced, stored, disclosed to any mation only". Reference should always be ma	third party or used for any purpose r de to the on-line EDMS for the updat	not authorized by Ned version	lorth Oil Company. Printed	