Company 1	Project Name			Logo 2					
Close Out Sheet									
PSD-HUC-017	MRU Barge Campaign Post S	Due Date:	2021-03-27						
Activity	Node	Facility		Priority					
		BRG-CPP							
Project Phase Guideword									
MRU Integration Project Post-Shutdown Phase									
Causes									
Inadequate separation between air intake and exhaust, or distance from hazardous area  Current proposed habitat ducting is 5m in length and blower has been sized considering this ducting length									
Safeguards									
Consequences  Unsafe conditions due to improper ventilation - Source of ignition causing Increased risk of fire & explosion in event of hydrocarbon LOPC, resulting in personnel injuries / fatalities, major platform asset and environmental impacts.									
Initial risk	Residual Risk								
None  Recommendations/ Action	No	ne							
To review proposed habitat locations and establish additional consumables and spares required for safe routing of pressurized habitat air intake and exhaust duction, and reflect in TEC list.									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs				Status
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed