Company 1	Project Name			Logo 2					
Close Out Sheet									
PSD-HUC-056	MRU Barge Campaign Post S	Due Date:	2021-04-10						
Activity	Node	Facility		Priority					
Project Phase	oject Phase BRG-CPP Guideword								
MRU Inte	gration Project Post-Shutdown Phase								
Causes									
Improper / inadequate work area controls, restrictions or isolations during radiography activities, incorrect work method / sequence									
Safeguards									
Consequences Unsafe conditions leading to personnel health issues due to exposure to radioactive material.									
Initial risk	Res	sidual Risk							
None	No	ne							
Recommendations/ Actions									
To ensure role of RPO is described in Offshore Post-Shutdown HUC Work Packs - Certified RPO onboard AWB during transfer from shore and during work activities at BRG-CPP									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs				Status
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed