Company 1	Project Name			Logo 2				
Close Out Sheet								
PSD-HUC-063	MRU Barge Campaign Post Shutdown Phase CRA			Due Date:	2021-04-10			
Activity	Node	Facility		Priority				
	BRG-CPP		BRG-CPP					
Project Phase Guideword		Guideword						
MRU Integration Project Post-Shutdown Phase								
Causes								
Inadequate / incorrect inspection for new Ex-rated equipment, i.e. not performing detailed inspections for new equipment Incompetent / Uncertified persons performing Ex-rated equipment installation, inspections and verifications, i.e. personnel without IECEx Certificate of Personnel Competence (CoPC)								
Safeguards								
Consequences Source of ignition at hazardous classified area on platform during normal operations, leading to increased risks of fire and explosion in event of gas leaks								
Initial risk	Res	idual Risk						
None	No	ne						
Recommendations/ Actions								
To ensure requirement for IECEx Certificate of Personnel Competence (CoPC) as per Contract requirement for Ex equipment installation and inspection are implemented, e.g. Supervisor with Ex-003 and inspection of Ex-rated equipment (Ex-001/007/0008). To update Project mobilization Plan and HUC work packs as required.								

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed