| Company 1 | Project Name | | | Logo 2 | | | | | |
|---|---------------------------------|--------------|------------|----------|--|--|--|--|--|
| Close Out Sheet | | | | | | | | | |
| PSD-HUC-016 | MRU Barge Campaign Post S | Due Date: | 2021-04-10 | | | | | | |
| Activity | Node | Facility | | Priority | | | | | |
| Project Phase | Project Phase BRG-CPP Guideword | | | | | | | | |
| . 10,000 | | | Guideword | | | | | | |
| MRU Integration Project Post-Shutdown Phase | | | | | | | | | |
| Causes | | | | | | | | | |
| Inadequate separation between air intake and exhaust, or distance from hazardous area | | | | | | | | | |
| Current proposed habitat ducting is 5m in length and blower has been sized considering this ducting length | | | | | | | | | |
| Safeguards | | | | | | | | | |
| Consequences Unsafe conditions due to improper ventilation - Source of ignition causing Increased risk of fire & explosion in event of hydrocarbon LOPC, resulting in personnel injuries / fatalities, major platform asset and environmental impacts. | | | | | | | | | |
| Initial risk | Residual Risk | | | | | | | | |
| None | No | ne | | | | | | | |
| Recommendations/ Actions | | | | | | | | | |
| To ensure adequate consumables and spares for air intake and exhaust ducting are available at site to satisfy habitat procedure requirement for separation of at least 5m away from hazardous area, e.g. additional ducting, adequate or larger blower fan capacity, etc. | | | | | | | | | |

| Response | | | | | |
|--|--|------------|----------|-------|----------------------------|
| None | | | | | |
| Remarks | | | Actionee | | |
| | | | | | |
| Attachments | | | | | |
| | | | | | |
| Organisation | MMHE | Signature: | Date: | | |
| Disipline and Subdisiplin | ne HUC | Signature: | | Date: | |
| COMPANY COMMENT | rs | | | | Status |
| | | | | | Agree |
| | | | | | Agree with comments |
| | | | | | Disagree |
| | | | | | To be followed |
| COMPANY Lead Discipli | ne: | Signature: | | Date: | |
| COMPANY Lead Safety: | | Signature: | | Date: | |
| COMPANY Rep (Engineering Coordinator): | | Signature: | | Date: | |
| | ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info | | | | Jorth Oil Company. Printed |