Company 1	Project Name			Logo 2					
Close Out Sheet									
PSD-HUC-129	MRU Barge Campaign Post S	Due Date:	2021-04-10						
Activity	Node	Facility		Priority					
		I	BRG-CPP						
Project Phase Guide			Guideword						
MRU Inte									
Causes									
Loss of power to lighting and essential equipment during night work activities - Marine Vessels									
Safeguards									
Consequences  Unsafe conditions, Unsafe acts - resulting in personnel injuries / fatality due to falls, man-overboard, incorrect handling of energized tools or equipment, adverse weather, etc.									
Initial risk	Residual Risk								
None  Recommendations/ Action  If FCB can be used	No.  s for transferring adsorbent cat c		ramic ball drums	, to conf	irm and				
verify adequacy of lighting fixtures for night work activities on FCB during vessel inspection. If vessel there is inadequate lighting, to ensure additional lighting fixtures are provided.									

Response						
None						
Remarks			Actionee			
Attachments						
Organisation	MMHE	Signature:		Date:		
Disipline and Subdisipline		Signature:		Date:		
COMPANY COMMEN	TS				Status	
					Agree	
					Agree with comments	
					Disagree	
					To be followed	
COMPANY Lead Discipli	ne:	Signature:		Date:		
COMPANY Lead Safety:		Signature:		Date:		
COMPANY Rep (Engineering Coordinator):		Signature:		Date:		
The information contained in this o	document is the proprietary to North Oil Company. It mus documents are uncontrolled and considered as "for infor	t not be reproduced, stored, disclosed to any	third party or used for any purpose of the to the on-line EDMS for the update	not authorized by Need version	lorth Oil Company. Printed	