Company 1	Project Name			Logo 2				
Close Out Sheet								
PSD-HUC-044	MRU Barge Campaign Post Shutdown Phase CRA			Due Date:	2021-04-10			
Activity	Node			Priority				
Project Phase			BRG-CPP Guideword					
MRU Inte								
Causes								
Improper work area isolation or controls for blasting activities								
Safeguards								
Consequences 1. Unsafe conditions from blasting garnet / debris at work areas and access ways leading to personnel injuries due to slips, trips or falls and asset impact requiring clean-up and repair / rectifications if damaged. 2. Personnel respiratory illness due to inhalation of blasting garnet / debris.								
Initial risk	Residual Risk							
None	No	ne						
Recommendations/ Actions								
To review current work pack and procedure for blasting and painting works and ensure safe work area controls are clearly described for Offshore work activities at CPP, e.g. work site preparation, restrictions of concurrent work in close proximity, material storage location and handling, debris waste management, etc.								

Response						
None						
Remarks			Actionee			
Attachments						
Organisation	MMHE	Signature:	ture: Date:			
Disipline and Subdisiplin	^{ne} Technical Safe	Signature:		Date:		
COMPANY COMMENT	TS			Status		
					Agree	
					Agree with comments	
					Disagree	
					To be followed	
COMPANY Lead Discipli	ine:	Signature:		Date:	•	
COMPANY Lead Safety:		Signature:		Date:		
COMPANY Rep (Engineering Coordinator):		Signature:		Date:		
The information contained in this d	document is the proprietary to North Oil Company. It mus documents are uncontrolled and considered as "for infor	it not be reproduced, stored, disclosed to any mation only". Reference should always be ma	third party or used for any purpose r de to the on-line EDMS for the updat	not authorized by Ned version	Jorth Oil Company. Printed	