Company 1	Project Name			Logo 2					
Close Out Sheet									
PSD-HUC-016	MRU Barge Campaign Post Shutdown Phase CRA				2021-03-27				
Activity	Node	Facility		Priority					
		BRG-CPP							
Project Phase			Guideword						
MRU Integration Project Post-Shutdown Phase									
Causes									
Inadequate separati	ion between air intake and exha	ust, or c	listance from ha	zardous	area				
Current proposed habitat ducting is 5m in length and blower has been sized considering this ducting length									
Safeguards Safeguards									
Consequences Unsafe conditions due to improper ventilation - Source of ignition causing Increased risk of fire & explosion in event of hydrocarbon LOPC, resulting in personnel injuries / fatalities, major platform asset and environmental impacts.									
Initial risk	Res	idual Risk							
None	No	ne							
Recommendations/ Actions									
To ensure adequate consumables and spares for air intake and exhaust ducting are available at site to satisfy habitat procedure requirement for separation of at least 5m away from hazardous area, e.g. additional ducting, adequate or larger blower fan capacity, etc.									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed