Company 1	Project Name			Logo 2				
Close Out Sheet								
PSD-HUC-108	MRU Barge Campaign Post Shutdown Phase CRA			Due Date:	2021-04-10			
Activity	Node	Facility		Priority				
			BRG-CPP					
Project Phase Guideword		Guideword						
MRU Integration Project Post-Shutdown Phase								
Causes								
Inadequate isolation from live platform process system - e.g. flare header (Positive isolation required)								
Safeguards								
Consequences  Hydrocarbon ingress into vess and environmental impact.	sel being worked on, increased risk of fire and e	explosion res	sulting in personnel injur	ies / fatalitie	s, major asset			
Initial risk	Re	sidual Risk						
None	No	ne 						
Recommendations/ Actions								
To ensure a rated blind flange is installed or other adequate means implemented for Gas / Condensate MRU vessel line connected to flare system, prior to vessel entry works, to satisfy the positive isolation requirement (as per Note 5 reflected in P&ID). To then reflect requirement in Work Pack and JSA, prior to opening of vessel man-hole.								

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	<sup>ne</sup> Commissioninç	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
The information contained in this d	ocument is the proprietary to North Oil Company. It must documents are uncontrolled and considered as "for inform	not be reproduced, stored, disclosed to any nation only". Reference should always be ma	third party or used for any purpose of the to the on-line EDMS for the update	not authorized by Ned version	lorth Oil Company. Printed