Company 1	Project Name				Logo 2				
Close Out Sheet									
PSD-HUC-020	MRU Barge Campaign Post Shutdown Phase CRA				2021-04-10				
Activity	Node	Facility	Facility						
			BRG-CPP						
Project Phase Guideword									
MRU Inte									
Causes									
Incompatible / Incorrect connection types or methods for water supply									
Safeguards									
Consequences Unsafe conditions or Unsafe acts (e.g. unauthorized modifications, make shift fittings, etc.) resulting in increased risk of personnel injuries / fatality and equipment / asset damage due to hose or fitting burst-of									
Initial risk	Residual Risk								
None Recommendations/ Actions To ensure temporary equipment and ship loose items (hose, fittings, etc.) are adequately preserved after pre-mobilization inspection. To describe requirement in Project Packing and									
Preservation Proced	dure.								

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed