Company 1	Project Name			Logo 2				
Close Out Sheet								
PSD-HUC-093	MRU Barge Campaign Post Shutdown Phase CRA				2021-03-27			
Activity	Node	Facility		Priority				
Project Phase			BRG-CPP Guideword					
			Guideword					
MRU Integration Project Post-Shutdown Phase								
Causes								
Incorrect leak test pressure as per Project requirement								
Safeguards								
Consequences Unable to carry out leak tests as planned, resulting in reworks and delays to complete work campaign.								
Initial risk	Res	idual Risk						
None	Noi	ne						
Recommendations/ Actions								
To ensure proposed Test Work Pack.	d leak test pressure are reviewe	d and aલ્	greed with Hess	, as part	of Leak			

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed