Company 1	Project Name				Logo 2				
Close Out Sheet									
PSD-HUC-067	MRU Barge Campaign Post Shutdown Phase CRA				2021-03-27				
Activity	Node	Facility		Priority					
			BRG-CPP						
Project Phase Guideword									
MRU Integration Project Post-Shutdown Phase									
Causes									
Unavailability of removed F&G detector and Field Instrument during Post-SD (platform live)									
Safeguards									
Consequences  Reduction of F&G detection coverage and Unavailability of monitoring instrument (PDIT) on Process - Prolonged isolation, extension of Inhibit / Override certificate requiring review and reassessment for adequacy of available controls / safeguards and mitigations for continued safe operations									
Initial risk	Res	idual Risk							
None	Noi								
Recommendations/ Actions  To perform during SD campaign or immediately after shutdown - Reinstatement of instrument and F&G detector removed during Pre-SD.									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed