Company 1	Project Name				Logo 2				
Close Out Sheet									
PSD-HUC-055	MRU Barge Campaign Post S	Due Date:	2021-03-27						
Activity	Node	Facility		Priority					
			BRG-CPP						
Project Phase Guidew									
MRU Integration Project Post-Shutdown Phase									
Causes									
Improper / inadequate work area controls, restrictions or isolations during radiography activities, incorrect work method / sequence									
Safeguards									
Consequences									
Unsafe conditions leading to personnel health issues due to exposure to radioactive material.									
Initial risk	Res	idual Risk							
None	No	ne							
Recommendations/ Actions									
To update Operations Interface Plan to reflect proposed RT source storage area, and review / finalize with Operations, prior to mobilization to site.									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed