Company 1	Project Name			Logo 2					
Close Out Sheet									
PSD-HUC-095	MRU Barge Campaign Post S	Due Date:	2021-03-27						
Activity	Node	Facility		Priority					
		ı	BRG-CPP						
Project Phase Guideword									
MRU Inte									
Causes									
Incompatible / Incorrect connection types / sockets or rating for electrical connections to test cabin									
Safeguards									
Consequences Unsafe conditions or Unsafe acts (e.g. unauthorized modifications, make shift fittings, etc.) leading to electrocution, Electrical arc flash resulting in personnel injuries / fatality and asset / equipment damage									
Initial risk	Residual Risk								
Recommendations/ Actions To ensure electrical power requirement and type of connection is described in Operations Support and Interface Plan (MMHE) including TEC list, if platform power is to be utilized.									

Response					
None					
Remarks			Actionee		
Attachments					
Organisation	MMHE	Signature:	Date:		
Disipline and Subdisiplin	ne HUC	Signature:		Date:	
COMPANY COMMENT	rs			Status	
					Agree
					Agree with comments
					Disagree
					To be followed
COMPANY Lead Discipli	ne:	Signature:		Date:	
COMPANY Lead Safety:		Signature:		Date:	
COMPANY Rep (Engineering Coordinator):		Signature:		Date:	
	ocument is the proprietary to North Oil Company. It mu documents are uncontrolled and considered as "for info				Jorth Oil Company. Printed