

Testy:

1. Check if no data passes during prog=1.
2. Check if data passes correctly to programmed address in port 0.
3. Check if data passes correctly to programmed address in port 1.
4. Check if data passes correctly to programmed address if address is max.
5. Check if data passes correctly to programmed address if address is min.
6. Check if data passes correctly to programmed address if data is max.
7. Check if data passes correctly to programmed address if data is min.
8. Check if no data passes if address was not programmed. (failed)
9. Check if no data passes if parity bit is wrong. (sometimes failed)
10. Check if no data passes if start bit is wrong. (sometimes failed)
11. Check if no data passes if stop bit is wrong. (sometimes failed)
12. Check if no data passes if parity bit is wrong, but with delay between packets.
(sometimes failed)
13. Check if no data passes if start bit is wrong, but with delay between packets.
(sometimes failed)
14. Check if no data passes if stop bit is wrong, but with delay between packets.
(sometimes failed)