


DB-D3100-V2.2

Page	Title	
01	COVER & SYS DIAGRAM	
02	D3100	
03	HDMI_IN_USB	
04	AUDIO_CVBS_IN	
05	POWER	
Date	Update History	BY
2022-1-18	Create the first version.	Terry
2022-4-8	Modify hotplug jitter	Terry
2022-9-27	add Reset	Terry




HDMI IN

[2]	HRX_D0P	HRX_D0P
[2]	HRX_D0N	HRX_D0N
[2]	HRX_D1P	HRX_D1P
[2]	HRX_D1N	HRX_D1N
[2]	HRX_D2P	HRX_D2P
[2]	HRX_D2N	HRX_D2N
[2]	HRX_D3P	HRX_D3P
[2]	HRX_D3N	HRX_D3N

[2]	HRX_HPD	HRX_HPD
[2]	HRX_SCL	HRX_SCL
[2]	HRX_SDA	HRX_SDA


Differential pairs Z0= 100 ohm

2 layer PCB Traces width 8mil



USB0/1

[2]	USB0PP	USB0PP
[2]	USB0PN	USB0PN
[2]	USB1PP	USB1PP
[2]	USB1PN	USB1PN







Zhuhai Hi-Chip Technology Co.,Ltd.

Size B	Document Number	Rev
	03_HDMI_IN_USB	V2.2
Date:	Tuesday, October 25, 2022	Sheet 3 of 5


LVDS

[2] LVDS-DN[0..7] <<< LVDS-DN[0..7]
 [2] LVDS-DP[0..7] <<< LVDS-DP[0..7]
 [2] LVDS-CN[0..1] <<< LVDS-CN[0..1]
 [2] LVDS-CP[0..1] <<< LVDS-CP[0..1]



CVBS_IN



[2] CVBS_IN <<< CVBS_IN



Audio DAC

I2S OUT


[2] I2S_DO <<< I2S_DO
 [2] I2S_BCLK <<< I2S_BCLK
 [2] I2S_LRCK <<< I2S_LRCK
 [2] I2S_MCLK <<< I2S_MCLK




Zhuhai Hi-Chip Technology Co., Ltd.

Size B Document Number 04_AUDIO_CVBS IN Rev V2.2
 Date: Tuesday, October 25, 2022 Sheet 4 of 5


VDDCORE 1.15V




VDDO 1.8V





VDD33 3.3V



BACKLIGHT



LCD VBIAS




ADC8B

[2] $ADC8B_IN0 \ll ADC8B_IN0$

IRRX

[2] IRRX $\ll$ ————— IRRX

DC5V



Zhuhai Hi-Chip Technology Co.,Ltd.

Size B	Document Number 05 POWER
-----------	-----------------------------

Rev	V2.2
-----	------

Date: Tuesday, October 25, 2022 Sheet 5 of 5