


## Implemented chain and its evidence boundary



Outer/keep ROI is inconsistent with target geometry. External motor transfer fails.  
Bag matching is not synchronized-window matching.