OUTPUTs

PACK+



MCU



INPUTs

we dont need 2 connectors because of the current, we have 2 connectors because we are putting 2 batteries in parallel for more capcity

Sense Lines



Pack In









Texas A&M University
Locked Inc.

Sheet: /
File: STAR_BMS.kicad_sch

Title: BMS

Size: A2	Date: 2026-01-14	**Rev: V1.0.0**
KiCad E.D.A. 9.0.5		Id: 1/1