0

Profile Selection Window

■ Basic operations on the profile selection window

Specify the profile number to extract with (1) or move the profile position cursor (green) (2).

To extract numerical data from the displayed profile, click the icon (3). Profile data is copied to the clipboard. Paste it into such worksheets as Excel sheets.

* When batch measurement is ON, start batch measurement by clicking the [Batch start] button (4) or executing another operation. Click the [Update hgt. img.] button to update displayed data.

