2D Display

■ 2D display

A profile at any arbitrary moment can be extracted from the height image display and shown side by side with the height image display.

This allows an extracted profile at any arbitrary moment and its OUT measurement values to be confirmed.

■ Basic operations on the display window

Specify the profile to extract by specifying the profile number on (1) or moving the profile position cursor (green) (2).

To confirm the trend result on a arbitrary X coordinate in the profile, click the icon of (3) to display the time axis profile cursor (yellow) (4) and the time axis profile on the window (5).

Move (4) to an appropriate position to display the time axis profile on the specified coordinate on (5).

To extract numerical data from the displayed profile, click the icon of (6) or (7).

Profile data is copied to the clipboard.

Paste it into such worksheets as Excel sheets.

