

Emergency Mitigation & Water Extraction Report

RapidRestore Services LLC | Work Order RR-260914-882

Site Identity

Field	Value
Customer	Meridian Precision Components LLC
Loss Address	1820 Commerce Drive, Irving, TX 75061
Date of Loss	September 14, 2026
Work Order	RR-260914-882
Reported Cause	Sprinkler branch-line water discharge

Work Performed

Activity	Detail
Water extraction	Approx. 10,400 gallons
Affected area	Approx. 4,200 sq ft
Equipment isolated	3 production assets
Inventory moved	135 cartons
Preliminary cost	\$19,750

Property Inspection Report

Apex Property Inspection Group | September 16, 2026

Assignment

Field	Value
Insured	Meridian Precision Components LLC
Property	1820 Commerce Drive, Irving, TX 75061
Policy Number	CPP-9083147
Loss Date	September 14, 2026

Findings

The visible water source was a failed sprinkler branch-line fitting approximately 16 feet above Aisle N-4. The roof and exterior envelope showed no evidence of storm-related intrusion.

Damage

Category	Finding	Estimate
Building	Flooring, drywall, electrical	\$98,000
Machinery	3 production units	\$71,000
Inventory	Water-exposed components	\$79,200
Mitigation	Pending final invoice	\$19,750

Contractor Repair Estimate

PrimeBuild Restoration & Construction | Estimate PB-260918-331

Project Identity

Field	Value
Customer	Meridian Precision Components LLC
Property	1820 Commerce Drive, Irving, TX 75061
Loss Date	September 14, 2026
Estimate Number	PB-260918-331
Cause	Failed sprinkler branch-line fitting / accidental water discharge

Estimate

Scope	Amount
Flooring — 4,200 sq ft	\$42,000
Drywall	\$15,000
Electrical	\$41,000
Machinery — 3 units	\$71,000
Contents handling	\$13,000
General conditions	\$10,000
Total	\$192,000

Asset Reference

Machinery allowance covers MP-CNC-02, MP-CNC-04 and PKG-01.

Equipment Damage Assessment

TechServe Industrial Equipment | Report TS-260920-104

Site Identity

Field	Value
Customer	Meridian Precision Components LLC
Site	1820 Commerce Drive, Irving, TX 75061
Loss Date	September 14, 2026
Report Number	TS-260920-104

Equipment

Asset ID	Equipment	Estimate
MP-CNC-02	CNC Machining Center	\$31,000
MP-CNC-04	CNC Machining Center	\$23,000
PKG-01	Automated Packaging Line	\$17,000
TOTAL		\$71,000

Finding

No fourth production asset was identified as water damaged. The three asset IDs correspond with the contractor estimate.

Claim Correspondence — Supporting Documents

Email printout | Claim CLM-2026-004817

Email Header

Field	Value
From	Thomas Lee
To	Rachel Morgan
Subject	CLM-2026-004817 — Supporting documents for September 14 warehouse water loss
Date	September 21, 2026

Message

Attached are the PrimeBuild repair estimate, TechServe equipment assessment, inventory valuation and preliminary Business Income worksheet for the September 14 water loss at our Irving facility.

The three affected production assets are MP-CNC-02, MP-CNC-04 and PKG-01.

Attachment References

PB-260918-331 — Contractor Estimate

TS-260920-104 — Equipment Report

Sprinkler System Engineering Assessment

FireSafe Engineering Group | Report FSE-260923-77

Site

Field	Value
Insured	Meridian Precision Components LLC
Property	1820 Commerce Drive, Irving, TX 75061
Loss Date	September 14, 2026
Report Number	FSE-260923-77
Engineer	David Patel, PE

Opinion

The sprinkler branch-line fitting above Aisle N-4 exhibited localized corrosion and fracture. Based on available physical evidence, the most probable immediate cause of the water loss was failure of this fitting.

Scope Limitation

This report does not determine insurance coverage or whether maintenance obligations were satisfied.

Commercial Property Policy — Declarations

Policy CPP-9083147

Policy Identity

Field	Value
Policy Number	CPP-9083147
Named Insured	Meridian Precision Components LLC
Scheduled Property	1820 Commerce Drive, Irving, TX 75061
Policy Period	01/01/2026 – 01/01/2027
Carrier	Summit Harbor Insurance Company

Coverage

Coverage	Limit	Deductible
Building	\$2,500,000	\$25,000
Business Personal Property	\$1,250,000	\$25,000
Business Income & Extra Expense	\$600,000	72-hour waiting period

Insured Incident Report — Water Loss

Internal report | September 14, 2026

Incident Identity

Field	Reported Information
Policy Number	CPP-9083147
Insured	Meridian Precision Components LLC
Property	1820 Commerce Drive, Irving, TX 75061
Incident Date	September 14, 2026
Reported By	Thomas Lee, Facilities Director

Narrative

At approximately 2:42 PM, a sprinkler water-flow alarm activated. Facilities personnel found water discharging from a branch-line fitting above Aisle N-4. The affected zone was isolated at 2:55 PM. Approximately 4,200 square feet of warehouse floor and the adjacent packaging area were affected.

Three production assets and multiple inventory pallets were exposed. No employee injuries were reported.