	R11_R12	R21	R22	$R21_{-}$	R22_	$Transfert_vers_emballage$	$Retour_Etape_Initial$	\mathbf{m}_0
Produit_Brute	0	0	0	0	0	0	1	4
M11	1	0	0	0	0	0	0	0
M12	1	0	0	0	0	0	0	0
M2	0	1	0	0	0	0	0	0
M3	0	0	1	0	0	0	0	0
PF	0	0	0	1	1	0	0	0
$ m M_{30}$	0	()	0	()	()	1	0	0