
Color codes

		Load cells
	SENSOR	MOTHERBOARD
1	red	PWR (N\$5)
2	black	GND
3	white	A-
4	green	A+
5		GND (Shield)



	Stepper	
MOTOR	MOTHERBOARD	
1 red	N\$14	N\$19
2 black	+12V	+12V N\$16
3 white	N\$15	N\$15
4 green	N\$16	+12V
5 blue	+12V	N\$14
6 yellow	N\$19	