


CDScreen2



	Mach	Alpha	CD	CD Power-Off	CD Power-On	CA Power-Off	CA Power-On	
►	0.01	0.000	0.221	0.221	0.221	0.221	0.221	
	0.02	0.000	0.221	0.221	0.221	0.221	0.221	