


CDScreen2



	Mach	Alpha	CD	CD Power-Off	CD Power-On	CA Power-Off	CA Power-On	
►	0.10	0.000	0.212	0.212	0.212	0.212	0.212	
	0.50	0.000	0.205	0.205	0.205	0.205	0.205	