Hook up all encoders, button to 5V and ground.

328P

port configurations

use this for interrupts PCMKS2

portd arduino pins pendulum component cart or pend? wire colors

PORTD for reading encoders

7	6	5	4	3	2	1	0	
PCINT23	PCINT22	PCINT21	PCINT20	PCINT19	PCINT18	PCINT17	PCINT16	
PD7	PD6	PD5	PD4	PD3	PD2	PD1	PD0	
digital pin 7	digital pin 6	digital pin 5	digital pin 4	digital pin 3	digital pin 2	digital pin 1	digital pin 0	
		rotary encoder	rotary encoder	rotary encoder	rotary encoder			
		cart	cart	pendulum	pendulum			
		green	white	white	green			

PORTB for PWM

PORTB arduino pins

pendulum component

PORTC arduino pin pendulum component I298n connection

7	6	5	4	3	2	1	0
crystal	crystal	digital 13	digital 12	digital 11	digital 10	digital 9	digital 8
							state transition
						PWM	button

PORTC for motor direction control

7	6	5	4	3	2	1	0	
?	reset	ai5	ai4	ai3	ai2	ai1	ai0	
						motor control	motor control	
						IN1	IN2	