

Product Quality Inspection Example																			
inspect_id	check_date	issue	inspector	check_mode	action	prod_code	batch_no	prod_line	supplier	sample_n	defect_n	defect_pct	severity	measure	tolerance	equip_id	shift	review	remarks
A7K2M9Q4T6X1	2026-01-05	Seal ring does not close tightly	QA1A07	Warehouse sampling	Scrap and remelt	PRD-A101	BT260105A	LINE-01	SUP-A17	80	6	7.50	Critical	0.82	0.50	EQ-A101	Day	Verified	Seal pressure test failed
B8L3N0R5U7Y2	2026-01-12	Crack on nut surface	QC2B14	Production line	Product recall	PRD-B205	BT260112B	LINE-02	SUP-B28	120	9	7.50	Critical	1.36	0.80	EQ-B207	Swing	Verified	Crack length exceeds acceptance limit
C9M4P1S6V8Z3	2026-02-03	Porosity in welded seam	QE3C21	Customer complaint	After-sales repair	PRD-C309	BT260203C	LINE-03	SUP-C39	1	1	100.00	Major	2.10	1.20	EQ-C315	Night	Follow-up	Unit replaced and retested on site
D0N5Q2T7W9A4	2026-02-18	Coating peeling from product housing	QF4D28	Warehouse sampling	Product recall	PRD-D412	BT260218D	LINE-01	SUP-D40	100	5	5.00	Major	0.48	0.30	EQ-D426	Day	Verified	Same batch isolated for inspection
E1P6R3U8X0B5	2026-03-06	Poor contact at power connector	QG5E35	Production line	Scrap and remelt	PRD-E518	BT260306E	LINE-04	SUP-E51	150	12	8.00	Critical	3.70	2.00	EQ-E538	Swing	Verified	Contact resistance exceeds limit
F2Q7S4V9Y1C6	2026-03-21	Excessive bearing rotation noise	QH6F42	Customer complaint	After-sales repair	PRD-F623	BT260321F	LINE-02	SUP-F62	1	1	100.00	Major	68.40	55.00	EQ-F649	Night	Follow-up	Normal operation after repair
G3R8T5W0Z2D7	2026-04-09	Assembly dimension exceeds tolerance	QJ7G49	Warehouse sampling	Scrap and remelt	PRD-G734	BT260409G	LINE-03	SUP-G73	90	7	7.78	Critical	0.34	0.20	EQ-G752	Day	Verified	Repeat measurement remains out of tolerance
H4S9U6X1A3E8	2026-04-27	Damaged moisture-proof package seal	QK8H56	Production line	Product recall	PRD-H845	BT260427H	LINE-04	SUP-H84	110	8	7.27	Major	4.20	2.50	EQ-H864	Swing	Verified	Entire batch placed on shipping hold