

Connector pinouts for x2 crossover cables.
For stright cables – flip lef/right.

Mac side signal names

