

Task-2

Group-2

Ankush Choudhary

Rasberry Pi Pico Conveyor belt using Color Sensor and Servos





/iolations (51) Unconnected Items (0) Schematic Parity (
 Error: Clearance violation (netclass 'Default' clearance Pad 1 [unconnected-(U2-NC-Pad1)] of U2 on F.Cu 	ance 0.2000 mm; actual 0.1500 mm)
Pad 2 [Net-(M1-+)] of U2 on F.Cu	
✓ Error: Clearance violation (netclass 'Default' clearance)	ance 0.2000 mm; actual 0.1500 mm)
Pad 2 [Net-(M1-+)] of U2 on F.Cu	
Pad 3 [Net-(M1)] of U2 on F.Cu	
 Error: Clearance violation (netclass 'Default' clearance) 	ance 0.2000 mm; actual 0.1500 mm)
Pad 3 [Net-(M1)] of U2 on F.Cu	Click on items to highlight them on the l
Pad 4 [unconnected-(U2-NC-Pad4)] of U2 on F.Cu	click of items to highlight them of the i
 Error: Clearance violation (netclass 'Default' clearance) 	ance 0.2000 mm; actual 0.1500 mm)
Pad 5 [Net-(U1-GPIO20)] of U2 on F.Cu	
Pad 6 [Net-(U1-GPIO21)] of U2 on F.Cu	
 Error: Clearance violation (netclass 'Default' clearance) 	ance 0.2000 mm; actual 0.1500 mm)
Pad 6 [Net-(U1-GPIO21)] of U2 on F.Cu	
Pad 7 [Net-(U1-GPIO19)] of U2 on F.Cu	