ISC	ISOLATION CERTIFICATE															th	panglong			
	IC Number:				20/0	700	04a					STATUS:	Request		]	ьото	box: Test k	ey number	30114	TOTAL ATTITUTE COMPANY
SECTIO	N 1: REQUEST																			
Isolation Designed by: Ad			Admisnistrator Designation: CNTT Date/Time: 20-Jul-20 00:00												-20 00:00					
Equipment to be isolated:										Test key number										
Reason for isolation: Test key number																				
SECTIO	N 2: REVISION AND AU	JTH	ORIZ	ZAT	ION															
	APPROVE FOR ISOLAT	101	l:					_					CONFIRM THE	$\overline{}$	MENT IS	s "ISO	LATED":			
										time:		VSP Sup				Date/time: Date/time:				
	ON TO TEST:							D.	ate/time:			,	CONFIRM THE SANCTION TO T			IS "ADDITED":	Date/time.			
										time:		VSP Sup Date/t				Date/time:				
AAAPPROVE FOR DE-ISOLATION:					Date/time:							CONFIRM THE EQUIPMENT IS "DE-ISOLATED":					Dute/time.			
VSP Sup					Date/time:								VSP Sup Date/time							
AA									D	ate/	time:		AA Date/tim							
SECTIO	N 3: CROSS REFERENCE	D'S	CEF	RTIF	FICAT	TES	6													
PTW CON			NECTING:									CSEC C	ONNECTING		1 [	ISOLATION/OVERRID		N/OVERRIDE CE	E CERTS	
							$\dashv$		$\vdash$											
SECTION 4: ELECTRICAL ISOLATION																				
No#	Isolation Tag name	ame APPLY ISOLATION SANCTION TO (Tick for applicable)												TO TEST			DE-ISOLATION			
					Т	Ţ		k fo	or app	licat			VSP Sup	Authorized Isolator		lator	VSP Sup Authorized		ator	Authorized Isolator
		sker	Push Button		hed	200	Disconnect Proved Deac		p g	2	Key numbe	Isolator signed <b>ON</b>	select de-isolation points	conf	irm appl	ied	request Re-isolatio	n confirm appli	ed	signed <b>OFF</b>
		Breaker							Tagged			signed ON	pomits							
1	11111	☑		☑				1   [		] 1:	234									
						H		+				<u> </u>								
							+	+	+	+										
SECTIO	N 5: VALVES ISOLATIO	N						t												
No# Isolation Tag name APPLY ISOLATION SANCTION TO TEST												TO TEST			DE-ISOLATION					
				В	$\top$	Т	(Tick	k fo	r appl			Authorized	VSP Sup	Autho	rized Isol		VSP Sup Authorized		ator	Authorized Isolator
		۱	Closed	B		] :	Locked				Key number	Isolator	select de-isolation		irm appl		request Re-isolatio			signed <b>OFF</b>
		l			Tag			1	$\perp$			signed <b>ON</b>	points							
1	22222	☑	Ш	  M		[	1	+	+	2.	222									
								$\dagger$												
				-	_	+	+	+	+	+										
						t		$\dagger$		+										
								1												
					-	-	+	+	+	+										
						+	+	+	+	+										
						İ		İ												
						1		1		_										
			$\vdash$	H	+	+	+	+	+	+										
				T	$\perp$	t	+	$\dagger$	$^{+}$	+										
				Г	Г	I	T	Ţ	T	T										
			$\vdash$	$\vdash$	+	+	+	+	+	+		-								
			$\vdash$	H	+	+	+	+	+	+										
						I		1	1	1										
			$\vdash$	_	-	+	+	+	+	+								-	_	
			$\vdash$	H	+	+	+	+	+	+										
			İ	T	İ	T	1	Ţ	_											
							$\perp$		T			-								
SECTIO	N 6: POSITIVE ISOLATION	) NI					_		_											
No#	Isolation Tag name	S14					APP	LY	ISO	LATI	ION		CANCELLEAURA							
140#	.solution rug name	+		_	_	_			r app				SANCTION TO TEST  VSP Sup Authorized Isolator VSP Sup Authorized Is							DE-ISOLATION
		Disconnect	eq	ed		7	5				Ser	Authorized Isolator	VSP Sup select de-isolation		<b>rized Iso</b> l irm appl		VSP Sup request Re-isolatio	Authorized Isolo n confirm appli		Authorized Isolator signed OFF
		Disco	Spaded	Blanked	Tag	payor	LOCK				Key number	signed <b>ON</b>	points							
1	3333	Ø		Ø		Ē		1			33333									
			$\vdash$	-	+	+	+	+	+	+		-								
				l	1	t	_	$\dagger$	_	_				L				<u> </u>		
								T	1											
Th: 6					<u> </u>															
	rm is auto-generated by int out copy is the only									requ _	uired				_					