







Slightly browned EVA in the centre of the cell with photobleaching at the edges [Köntges14].



Single cell browned much faster than the others due to local heating [Köntges14].



Encapsulant delamination from cell along grid fingers and bus bar [Packard12].



Encapsulant delamination along a bus-bar in a cell close to the module edge [Moser17].

