





Glass breakage of tempered glass induced by burn mark [Köntges17]. (see also PVFS 1-7 and PVFS 1-9)



Glass breakage caused due to poor clamp design [Köntges17]. (see also PVFS 3-1)



Hail damage [By the courtesy of SUPSI PVLab].

