



Continuous shading caused by chimney [By courtesy of SUPSI PVLab].



Missing maintenance on flat green roof [By courtesy of SUPSI PVLab].

