Architetture dei Sistemi di Elaborazione 02GOLOV [A-L]

Delivery date: Wednesday, October 30, 2019


Laboratory 2

Expected delivery of lab_02.zip must include: program 2.s and program 3.s

This file, filled with information and possibly compiled in a pdf format.

Please, configure the winMIPS64 simulator with the Base Configuration provided in the following:

- Code address bus: 12
- Data address bus: 12
- Pipelined FP arithmetic unit (latency): 6 stages
- Pipelined multiplier unit (latency): 8 stages
- divider unit (latency): not pipelined unit, 24 clock cycles
- Forwarding is enabled
- Branch prediction is disabled
- Branch delay slot is disabled
- Integer ALU: 1 clock cycle
- Data memory: 1 clock cycle
- Branch delay slot: 1 clock cycle.



1) Write an assembly program (program 2.s) for the winMIPS64 architecture described before able to implement the following piece of code described at high-level:

```
for (i = 0; i < 30; i++){
v5[i] = (v1[i]*v2[i]) + v3[i];
v6[i] = (v3[i]*v4[i])/v5[i]:
```

Assume that the vectors v1[], v2[], v3[], and v4[] are allocated previously in memory and contains 30 double precision floating point values; assume that v5[] will not contain 0 values. Additionally, the vectors v5[], v6[] are empty vectors also allocated in memory.

- a. Using the simulator and the *Base Configuration*, compute how many clock cycles take the program to execute.
- 2) Using the WinMIPS64 simulator, validate experimentally the Amdahl's law, defined as follows:

follows:
$$speedup_{overall} = \frac{execution time_{old}}{execution time_{new}} = \frac{1}{(1 - fraction_{enhanced}) + \frac{fraction_{enhanced}}{speedup_{enhanced}}}$$

- a. Using the program developed before: program 2.s
- b. Modify the processor architectural parameters related with multicycle instructions (Menu→Configure→Architecture) in the following way:

- 1) Configuration 1
 - Starting from the *Base Configuration*, change only the FP addition latency to 3
- 2) Configuration 2
 - Starting from the *Base Configuration*, change only the Multiplier latency to 4
- 3) Configuration 1
 - Starting from the *Base Configuration*, change only the division latency to 12

Compute by hand (using the Amdahl's Law) and using the simulator the speed-up for any one of the previous processor configurations. Compare the obtained results and complete the following table.

Table 1: program_2.s speed-up computed by hand and by simulation

Proc. Config.	Base config. [c.c.]	Config. 1	Config. 2	Config. 3
Speed-up comp.				
By hand	1386	1.069	1.095	1.351
By simulation	1386	1.045	1.095	1.351

3) Write an assembly program (**program_3.s**) for the winMIPS64 architecture able to compute the hamming distance between two consecutive elements of a data array X[] previously allocated in memory (the array X contains 30 8-bit elements). Given two consecutive elements X[i] and X[i+1], the Hamming distance is defined as the number of bits set to 1 in (X[i] ^ X[i+1]).

If the Hamming distance is:

- even, the variable even_counter must be incremented
- odd, the variable odd counter must be incremented

These two variables are allocated in memory and initially empty.

- 4) Considering the following winMIPS64 architecture:
 - Code address bus: 12
 - Data address bus: 12
 - Pipelined FP arithmetic unit (latency): 4 stages
 - Pipelined multiplier unit (latency): 8 stages
 - divider unit (latency): not pipelined unit, 12 clock cycles
 - Forwarding is enabled
 - Branch prediction is disabled
 - Branch delay slot is disabled
 - Integer ALU: 1 clock cycle
 - Data memory: 1 clock cycle
 - Branch delay slot: 1 clock cycle.

a. calculate by hand, how many clock cycles take the program to execute?

	 <i>-</i>	1 0	_
Number of clock cycles:	1484		

b. compute the same calculation using the *winMIPS64* simulator.

Number of clock cycles:	510	
-------------------------	-----	--

Compare the results obtained in the points 4.a and 4.b., and provide some explanation in the case the results are different.

Eventual explanation:

La differenza del numero dei c.c. è dovuta ai salti condizionati: in alcuni cicli vengono eseguite meno istruzioni rispetto ad altri mentre nel calcolo a mano si è sempre considerato il "caso peggiore" (in cui vengono eseguite tutte le istruzioni, e quindi il numero di c.c. risulta più grande).

In particolare il numero di c.c. calcolati dalla simulazione dipende fortemente dall'input dato al programma.