
BLUEBOAT

CTD WINCH ASSEMBLY GUIDE



ASSEMBLY SEQUENCE

Build the individual mounts first, then assemble the winch platform and install it on the boat.

01 **Storage Platform**
3 illustrations

02 **Camera Mount**
3 illustrations

03 **CTD Mount**
4 illustrations

04 **Spool Mount**
2 illustrations

05 **Port Support**
6 illustrations


06 **Starboard Support**
2 illustrations


07 **Spool Support**
2 illustrations


08 **CTD Winch Platform**
21 illustrations


09 **BlueBoat Installation**
Final installation

01 / STORAGE PLATFORM










exploreHD

02 / CAMERA MOUNT





exploreHD

03 / CTD MOUNT



03 / CTD MOUNT




ASSEMBLY NOTE

Route the spool cable behind the bearing before completing this assembly.

03 / CTD MOUNT











05 / PORT SUPPORT



ASSEMBLY NOTE

Connect the motor cables before installing the motors.


05 / PORT SUPPORT



05 / PORT SUPPORT




05 / PORT SUPPORT



05 / PORT SUPPORT



05 / PORT SUPPORT



ASSEMBLY NOTE


To disconnect the motor cables, disassemble the port support, remove the caps, pull out the motors, then unplug the cables.

06 / STARBOARD SUPPORT



06 / STARBOARD SUPPORT






ASSEMBLY NOTE


Orient the spool so the cable can be pulled from the rear and underneath, as shown.

07 / SPOOL SUPPORT



ASSEMBLY NOTE

To disconnect the motor cables, disassemble the spool support and port support (see Port Support, Final Assembly).







ASSEMBLY NOTE

Insert the T-nuts at this stage, before the slots become inaccessible.





08 / CTD WINCH PLATFORM







ASSEMBLY NOTE

Insert the T-nuts at this stage, before the slots become inaccessible.

08 / CTD WINCH PLATFORM




08 / CTD WINCH PLATFORM




ASSEMBLY NOTE

Insert the T-nuts at this stage, before the slots become inaccessible.




ASSEMBLY NOTE

Position the motors on the port side, as shown.



ASSEMBLY NOTE

Insert the T-nuts at this stage, before the slots become inaccessible.








ASSEMBLY NOTE


Insert the T-nuts at this stage, before the slots become inaccessible.





























ASSEMBLY NOTE


Position the spool aft and the CTD forward. Ensure the crossbar mounts are fully seated in the aluminium profiles so the platform fits easily onto the crossbars.







ASSEMBLY NOTE

If the screws do not align with the crossbar holes, adjust the platform position. First loosen the socket set screws in the T-slot corner connectors and the round-head screws in the corner brackets (see CTD Winch Platform, Step 5 and CTD Winch Platform, Step 7).





COMPLETED SYSTEM



CTD winch platform installed on the BlueBoat

REMOVAL FOR TRANSPORT

For carrying and transport, remove the CTD winch platform from the boat:

01 Open the port hatch and disconnect all cables. Lift the hatch lid clear of its hull compartment.

02 Remove the four funnel screws and detach the funnel.

03 Remove the two front screws that pass through the crossbar into the nuts underneath.

04 Remove the eight crossbar-mount screws, then take off the four caps.

05 Detach the camera mount and secure it safely on or inside the boat.

06 For easier transport, shorter aluminium profiles may be used with the CTD mount left attached. Carry the long profiles separately.

07 Move the hatch lid and CTD winch platform separately as needed.